

Monster Energy NASCAR Cup Series					
Infraction Date	Track	Team	Level	Infraction	Penalty
9/3/2017 (post-race inspection)	Darlington	No. 11	L1	Section 20.14.2 Rear Suspension I-4 f <i>Truck Trailing Arm Spacers/Pinion Angle Shims. Spacers/pinion angle shims must conform to the following drawing: A-008-01016d-16 REV. A. Notes: 6 The Truck trailing arm spacer / pinion angle shim mating surfaces must be planar and must be in complete contact with corresponding mating surfaces at all points and at all times. Race finish is encumbered per Section 12.10 Encumbered Race Finishes.</i>	Crew chief (Mike Wheeler) has been fined \$50,000 and suspended from two Monster Energy NASCAR Cup Series Championship Points Events. Team has been assessed with the loss of 25 owner points and 25 driver points.
9/3/2017 (post-race inspection)	Darlington	No. 88	Safety	Sections 10.9.10.4: Tires and Wheels <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Greg Ives) has been fined \$20,000 and suspended from the next Monster Energy NASCAR Cup Series Championship points event.

NASCAR XFINITY Series					
Infraction Date	Track	Team	Level	Infraction	Penalty
9/2/2017 (post-race inspection)	Darlington	No. 18	L1	Sections 20.14.2 Rear Suspension I-4 <i>Truck Trailing Arm Spacers/Pinion Angle Shims; h. Spacers/pinion angle shims must have single planar mating surfaces. Notes: All mating surfaces between the truck; trailing arm and the U-bolt saddle must be in complete contact with each other. Race finish is encumbered per Section 12.10 Encumbered Race Finishes.</i>	Crew chief (Eric Phillips) has been fined \$25,000 and suspended from two NASCAR XFINITY Series Championship Points Events. Team has been assessed with the loss of 25 owner points.
9/2/2017 (post-race inspection)	Darlington	No. 22	L1	Sections 20.14.2 Rear Suspension I-4 <i>Truck Trailing Arm Spacers/Pinion Angle Shims; h. Spacers/pinion angle shims must have single planar mating surfaces. Notes: All mating surfaces between the truck; trailing arm and the U-bolt saddle must be in complete contact with each other. Race finish is encumbered per Section 12.10 Encumbered Race Finishes.</i>	Crew chief (Greg Irwin) has been fined \$25,000 and suspended from two NASCAR XFINITY Series Championship Points Events. Team has been assessed with the loss of 25 owner points.